

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

UNION MILLS HOMESTEAD
3311 Littlestown Pike
Westminster
Carroll County
Maryland

HABS MD-1297

INDEX TO BLACK AND WHITE PHOTOGRAPHS

James W. Rosenthal, photographer, October 2007

| | |
|-----------|---|
| MD-1297-1 | General view of mill from south. |
| MD-1297-2 | Perspective view of mill from south. |
| MD-1297-3 | Perspective view of mill and house from west. |
| MD-1297-4 | Detail of mill wheel from northeast. |